

	A	B	C	D	E	E5	F	G	H	d	d1	d2	n°	ø	a	b	a1	b1	a2	b2
	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]
MAR 310	58	350	470	220	540	515	182	58	312	168	200	238	8	11	160	101	194	135	210	156
MAR 350	61	395	530	250	597	577	207	61	342	187	219	256	8	11	179	111	213	147	230	165
MAR 400	70	430	588	275	674	648	233	70	387	209	241	278	8	11	202	125	235	161	256	180
MAR 450	78	455	650	306	730	711	255	78	417	233	265	300	8	11	226	141	259	176	286	200
MAR 501	88	505	738	350	827	800	288	88	472	260	292	327	8	11	253	160	286	194	313	220
MAR 502	88	535	738	350	827	800	288	88	472	260	292	327	8	11	253	160	286	194	313	220
MAR 571	98	555	828	390	925	898	327	98	527	292	332	362	8	11	285	180	322	213	345	240
MAR 572	98	675	828	390	925	898	327	98	527	292	332	362	8	11	285	180	322	213	345	240
MAR 631	108	695	940	448	1028	676	368	108	582	350	380	410	8	11	320	200	356	235	380	260
MAR 632	108	695	940	448	1028	676	368	108	582	350	380	410	8	11	320	200	356	235	380	260
MAR 711	120	720	1048	500	1150	756	415	120	652	350	380	410	8	11	358	224	395	265	428	294
MAR 712	120	760	1048	500	1150	756	415	120	652	350	380	410	8	11	358	224	395	265	428	294
MAR 713	120	800	1048	500	1150	756	415	120	652	350	380	410	8	11	358	224	395	265	428	294

	n1xp	n2xp	n°	ø	I	J	K	L	M	N	O	P	Q	R	S	T	U	øb	Kg
	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	[mm]	
MAR 310	1x90	1x90	8	11	135	230	260	-	210	-	-	-	50	25	-	-	-	13	29
MAR 350	1x90	1x90	8	11	175	240	270	-	250	-	-	-	50	25	-	-	-	13	36
MAR 400	1x90	2x90	10	11	175	290	320	-	250	-	-	-	50	25	-	-	-	13	44
MAR 450	1x90	2x90	10	11	225	290	320	-	305	-	-	-	55	25	-	-	-	13	52
MAR 501	1x90	2x90	10	11	300	350	390	-	380	-	-	-	55	25	-	-	-	13	120
MAR 502	1x90	2x90	10	11	300	350	390	-	380	-	-	-	55	25	-	-	-	13	120
MAR 571	1x100	2x100	10	11	300	400	440	-	380	-	-	-	55	25	-	-	-	13	210
MAR 572	1x100	2x100	10	11	300	400	440	-	380	-	-	-	55	25	-	-	-	13	210
MAR 631	1x100	3x100	12	11	420	440	480	-	500	-	-	-	55	25	-	-	-	13	270
MAR 632	1x100	3x100	12	11	420	440	480	-	500	-	-	-	55	25	-	-	-	13	270
MAR 711	1x100	3x100	12	11	470	480	520	-	550	-	-	-	55	25	-	-	-	13	375
MAR 712	1x100	3x100	12	11	470	480	520	-	550	-	-	-	55	25	-	-	-	13	375
MAR 713	1x100	3x100	12	11	470	480	520	-	550	-	-	-	55	25	-	-	-	13	375