

Qv	SVA	80		100		125		150/160		200	
	r	10 mm	20 mm	10 mm	30 mm	10 mm	30 mm	10 mm	30 mm	10 mm	30 mm
20	Ps	15	7								
	Lth	<0,5	<0,1								
	Lw	21	<10								
40	Ps	50	25								
	Lth	2.70	2								
	Lw	48	31								
50	Ps	75	38	18	10						
	Lth	4	3	1	<0,5						
	Lw	59	41	15	<5						
60	Ps			28	15						
	Lth			1.80	1.10						
	Lw			29	<15						
70	Ps			35	17	20	7				
	Lth			2.50	1.70	2	0.50				
	Lw			34	24	20	<5				
100	Ps					40	18	30			
	Lth					3.50	2	2.70			
	Lw					28	14	29			

[illegible]